

#170 supp

STATE OF CONNECTICUT
BEFORE THE DEPARTMENT OF PUBLIC UTILITY CONTROL

In the Matter of the DPUC)
Investigation into Electric Capacity) Docket 99-08-01
and Distribution)

SUPPLEMENTAL TESTIMONY OF
PAUL CHERNICK
ON BEHALF OF
THE OFFICE OF CONSUMER COUNSEL

Resource Insight, Inc.
JANUARY 5, 2000

TABLE OF CONTENTS

I.	Introduction.....	1
II.	Company T&D Design and Maintenance Procedures.....	4
III.	Outage Data Collection.....	10
IV.	Distributed Utility Planning.....	12

1 **I. Introduction**

2 **Q: Please state your name, occupation and business address.**

3 A: I am Paul L. Chernick. I am the president of Resource Insight, Inc., 347
4 Broadway, Cambridge, Massachusetts 02139.

5 **Q: Are you the same Paul Chernick who previously filed testimony in this
6 proceeding?**

7 A: Yes.

8 **Q: What is the purpose of this supplemental testimony?**

9 A: I supplement my initial testimony based on (1) the testimony of utility
10 witnesses on the effects of the 1999 summer heat wave and (2) UI and CL&P
11 responses to discovery on the issue of distribution reliability

12 **Q: Please summarize this supplemental testimony.**

13 A: The outage experience in the 1999 summer heat wave confirms the need for
14 further review of utility T&D system design and operation practices. Future
15 proceedings on T&D reliability should consider at least the following issues:

- 16 • whether the T&D system design standards are adequate;
- 17 • whether the standards and procedures are consistently applied in both
18 the design of new systems and in the operation of existing systems;
- 19 • whether policies and procedures for the replacement of undersized
20 equipment provide a reasonable level of service quality, particularly for
21 residential customers;
- 22 • how closely the actual reporting of outage data follows written
23 procedures; and

- 1 • how DSM programs can be designed effectively to target specific areas
2 needing T&D upgrades or improved reliability.

3 Reviewing the Companies' T&D design and maintenance practices is a
4 necessary step in evaluating service quality and in implementing
5 performance standards. Given the number and complexity of the issues, I
6 recommend that the next stage of this investigation take the form of round-
7 table discussions.

8 **Q: What specific areas do you address in this supplemental testimony?**

9 A: I address the following areas:

- 10 • The appropriateness of the utilities' treatment of the 1999 summer heat
11 wave as a "storm,"
- 12 • The adequacy of the utilities' procedures for sizing, upgrading and
13 maintaining distribution equipment,
- 14 • The adequacy of utility efforts to improve the quality of outage data,
15 and
- 16 • The validity of the utilities' rejection of distributed utility planning.

17 **Q: Why have UI and CL&P labeled the 1999 summer heat wave a "storm?"**

18 A: UI and CL&P classify the 1999 summer heat wave as a "storm" under the
19 Department's criterion for excludable events:

20 ... a major storm will be declared when the number of interruption
21 restoration steps exceeds the 98.5 percentile of all days in the most
22 recent four years. (Attachment to IR OCC-UI-25)

23 CL&P identifies three separate periods, June 7-8, June 28-29, and July
24 3-7 as "storms." On UI's system, the outage experience on July 5 and 6 only
25 qualified as a "storm."

26 **Q: What outage events occurred on UI's system in the summer heat wave?**

1 A: There were four cable failures (one on July 5 and three on July 6), 121
2 transformer overloads, and 19 line fuse overloads. According to UI, the
3 occurrence of three cable failures in one day was not unprecedented, but the
4 high incidence of transformer and fuse overloads was abnormal.

5 All of the transformer failures and line fuse overloads occurred in
6 residential neighborhoods developed before 1980. The Company attributes
7 these overloads to additions of window air-conditioning units (Ostrum, pp. 1-
8 3, IR OCC-UI-9 and 10).

9 **Q: What distribution problems occurred on the CL&P system?**

10 A: The 1,500 transformers failures and overloads were the primary cause of
11 customer outages. Line fuse overloads were the second most frequent
12 problem. CL&P found that most of the overloads occurred in transformers
13 that were installed 25 to 30 years ago and resulted from customer additions
14 of air conditioning load. However, the Company identified two cases where
15 undersized transformers had been installed in new residential developments
16 (Direct testimony of D. L. Louth, pp. 4-6, IR 1-EL-3).

Chuck window
AC unit
Central AC

17 **Q: What is your concern about treating the heat wave as a “storm” to be
18 excluded from performance statistics?**

19 A: In Docket No. 86-12-03 (pp. 3-4), the Department explained that by
20 excluding major storm events, the reliability indices would be more useful
21 “in identifying reliability weaknesses and problems that can be controlled by
22 the Companies.” The exclusion of the summer distribution problems does not
23 serve the intended purpose, for two reasons:

24 First, equipment overloads were responsible for most of the outages last
25 summer. These outages were not the result of such physical causes as

1 lightning, high winds, wet snow and ice on the lines, or fallen trees. They
2 were load-related, and well within the control and responsibility of the utility.

3 Second, as CL&P itself demonstrates (B. G. Blakey Direct, p. 2), “the
4 summer of 1999 was extremely hot, but not unprecedented.” It may be too
5 costly to design a distribution system to operate under extreme conditions—
6 the heat wave of the century, for example—without significant service
7 interruptions. But the 1999 summer heat wave was not so unusual an event.

8 It is important that the designation of the heat wave as a “storm” not
9 obscure the utility’s responsibility for the service interruptions that occurred
10 because of undersized or inoperable equipment. As the Department stated in
11 Docket No. 86-12-03:

12 Customers understand outages due to nature, but outages caused by
13 inadequate system design, poor maintenance or equipment failure are
14 not acceptable (p. III-1)

15 II. Company T&D Design and Maintenance Procedures

16 **Q: What shortcomings have you identified in the Companies design and**
17 **maintenance practices that could have contributed to the service**
18 **interruptions last summer?**

19 **A:** The information provided by the Companies indicates deficiencies in the
20 following areas:

- 21 • Inadequate monitoring of loads on distribution transformers, particularly
22 in residential neighborhoods;
- 23 • Failure to replacement of heavily-loaded transformers before failure;
24 and

- 1 • Inadequacy of design standards and compliance with those standards, in
2 particular in the initial sizing of distribution equipment in new
3 residential developments.

4 **Q: To what extent do CL&P and UI monitor loads on transformers?**

5 A: CL&P monitors load on distribution substation transformers and transformers
6 serving large C&I customers, and evaluates upgrades in the case of additions
7 of new customers or of major additions to existing loads. But it does not
8 monitor loading on residential distribution transformers (OCC-CLP-31). In
9 fact, CL&P has abandoned the one monitoring device it had, the transformer
10 signal lamp:

11 ...Many single-phase, overhead CSP [completely self-protected]
12 transformers were supplied with secondary with signal lamps. The lamp
13 serves as a warning that the transformer is approaching an overload
14 condition. We no longer purchase overhead CSP transformers with
15 lamps, and do not presently change out transformers when the lamp is
16 lit. Utility companies nationwide are also moving away from this
17 practice. (Attachment to OCC-CL&P-32, p. 4, emphasis in the original)

18 UI claims to collect loading data on all types of transformers, including
19 distribution line transformers, “if UI expects a possible transformer thermal
20 overload”. (OCC-UI-22a, 22b). As I discuss below, it is not clear how this
21 policy translates into actual practice in the case of small residential line
22 transformers.

23 Without load monitoring, the utility cannot systematically identify
24 transformers that are vulnerable to future overloads and therefore, good
25 candidates for upgrading.

26 **Q: Does either utility have a mechanism for replacement of heavily-loaded**
27 **transformers before failure?**

1 A: CL&P does not upgrade residential transformers until they overload or fail
2 and customers are disconnected. (IR OCC-CL&P-32).

3 UI's practices are less clear. According to UI's Distribution System
4 Design Criteria, vulnerability to failure is not considered in UI's decision to
5 change out line transformers (Attachment to IR OCC-UI-29, pp. 24-25). On
6 the other hand, UI claims to do the following for each distribution
7 transformer:

- 8 • monitor energy sales,
- 9 • estimate peak load from the sales data,
- 10 • for transformers estimated to be above 80% of nameplate rating,
11 monitor loading during a peak period,
- 12 • replace transformers for which load exceeds the nameplate rating.

13 This sounds like a very conservative policy, since transformers will generally
14 operate for many hours at loads much higher than their nameplate rating.

15 It is unclear to what extent this practice applies to residential
16 transformers.

17 **Q: Why is it unclear?**

18 A: In most of UI's transformer outages this summer, load had reached between
19 120% and 150% of nameplate rating. (OCC-UI-33). UI attributes these peaks
20 to additions of air conditioning load, which had occurred over a number of
21 years. It is likely that loading had reached 100% of nameplate rating well
22 before the summer heat wave.

23 **Q: What replacement process does CL&P follow?**

24 A: Issue 28 of CL&P's Over & Under publication provides a description of
25 CL&P's procedures: The transformer's breaker is initially set for normal load
26 cycle, which allows for a peak load of limited duration in excess of the

1 nameplate rating of the transformer. If the transformer is overloaded, the
2 breaker is tripped and customers are disconnected.¹ CL&P does not replace
3 the transformer at this point. Instead, the response to overloading (absent any
4 secondary fault conditions) is to reset the breaker at the full-capacity
5 (“overload”) position to allow for greater overloading of the transformer.
6 Only after the breaker trips at the full-capacity position, disconnecting the
7 customers for a second time, will the transformer be replaced with a larger
8 unit. (Attachment to OCC-CL&P-32, pp. 4-5).

9 **Q: Is the current policy on early transformer replacement the result of a**
10 **cost-effectiveness analysis?**

11 A: No. Neither utility has studied the cost-effectiveness of replacement or relief
12 of heavily loaded transformers before failure. (IR OCC-CL&P-32f and OCC-
13 UI-23f)

14 Allowing a transformer to operate at loads higher than design reduces
15 its expected life, as well as decreasing service reliability. On the other hand,
16 if transformers are removed before they fail, they can be used at other
17 locations. Alternatively, the load served by an overloaded transformer can be
18 shared with an additional transformer, prolonging the life of the original unit
19 and improving reliability. The Companies replacement policy should be
20 reexamined to determine whether the cost savings from foregoing early
21 replacement of heavily-loaded transformers or relief justifies the reduction in
22 service quality and the premature aging of transformers.

¹ A transformer is designed to handle a normal load cycle, which allows for peaks that higher than nameplate rating, as long as they are compensated for by periods where the loads fall below the nameplate rating. An overload is “a sustained load substantially greater than the transformer’s nameplate rating.” (Attachment to IR OCC-CL&P-32, p. 4).

1 **Q: What problems with design standards and application of those**
2 **standards became apparent in the summer heat wave?**

3 A: In its review of the outages that occurred last summer, CL&P discovered that
4 some transformers installed in new residential developments had been
5 undersized. The Company recognizes that these outages were the result of
6 both inadequate design standards and inadequate compliance with those
7 standards. (IR DPUC-1-EL-3).

8 **Q: Does CL&P plan to take any action to correct this problem?**

9 A: Yes. CL&P plans to make the following changes:

- 10 • Revision of its design standard to specify the sizing of transformers for
11 homes greater than 3500 square feet, and
- 12 • Enhanced training for technicians “to insure distribution standards
13 regarding transformer sizing are understood and followed.” (IR DPUC-
14 1-EL-3).

15 **Q: Has either Company studied how well its technicians comply with design**
16 **standards and guidelines?**

17 A: No. Neither company has performed a study of the extent of compliance or
18 believes that such a study is needed. (OCC-CL&P-30, OCC-UI-21).

19 **Q: Is the this confidence that standards and guidelines are properly applied**
20 **well-founded?**

21 A: No. In UI view, it is enough that “[a]ll working leaders, field coaches and
22 engineers share responsibility for insuring that standards and guidelines
23 are complied with.” Mere assignment of job responsibility does not ensure
24 that mistakes will not be made.

25 And CL&P assures us that personnel from its Distribution Material and
26 Construction Standards Section visit each work center to verify compliance

1 with standards. However, as CL&P's experience last summer clearly
2 indicates, periodic inspections, while useful, are not sufficient to ensure
3 compliance.

4 The agenda for future proceedings or roundtable discussions should
5 include a review of the equipment sizing standards and the extent of
6 compliance with those standards.

7 **Q: Do the Companies have any plans to alter their load monitoring, sizing
8 and replacement practices to prevent a recurrence of the summer heat
9 wave outage experience?**

10 A: It appears that UI does not plan to make any major changes in its transformer
11 sizing and replacement practices. (Ostrum Direct).

12 CL&P's plans are less clear. On one hand, CL&P states that it "does not
13 plan to change the process for managing load growth on distribution
14 transformers."² (IR OCC-CL&P-42). On the other hand, CL&P has specified
15 two changes it intends to make to improve the initial sizing of transformers in
16 new developments, as discussed above. In addition, CL&P recognizes that it
17 needs to conduct a broad review of its current procedures in light of the
18 abnormal number of transformer outages last summer:

19 The high number of distribution transformers which tripped/failed
20 suggest some value in reviewing past transformer load management
21 studies for current applicability (if any), as well as existing practices for
22 initial sizing, and managing load growth. Specifically, System
23 Engineering will be requested to:

- 24 • Review past transformer load management studies and recommend
25 a course of action

² According to the response to IR OCC-CL&P-42, the "process for managing load growth" includes such actions as initial sizing of transformers, upgrades due to known load growth and/or voltage complaints and addressing protective device operations.

- 1 • Review 2 or 3 newer developments from each region that had
2 transformer trippings. Review compliance of sizing with standards
3 and adequacies of standards in light of experience.
- 4 • Review methods of managing load growth on transformers (e.g.,
5 service upgrades, new homes connected, red light indications) and
6 recommend any changes necessary. (CL&P's July 3-7 Heat Storm
7 report, p. 10, provided as an attachment to IR OCC-CL&P-8)

8 This inconsistency in its discovery responses suggests that CL&P is unclear
9 itself about how it will proceed in addressing the summer outage experience.

10 **III. Outage Data Collection**

11 **Q: Please describe each Company's data collection process**

12 A: The system is similar for the two companies. Essentially, the customer call
13 initiates the outage report, the dispatcher records the call, and the line crew
14 confirms the outage at the trouble location. Additional information from the
15 field and from the database is entered by the dispatcher to complete the
16 record for the outage. (OCC-CL&P-25, OCC-UI-16).

17 **Q: Do the Companies' outage-data systems meet the minimum**
18 **requirements for accurate data collection?**

19 A: The Companies have developed some useful data and have, to some extent,
20 automated their systems.³ However, the data collection relies substantially on
21 manual reporting. Manual inputs are more subject to error than automatic
22 recording. In addition, in the case of distribution outage reporting, the
23 process requires input from employees whose primary responsibility is not

³ For example, UI has detailed data on customer count "on each device such as on transformers, fuses, disconnects, ABS, reclosers, etc.," but these customer counts are not currently shown on the utility's GIS system. ("Storm Floyd Critique Notes," p. 1. Attachment to IR OCC-UI-4)

1 data collection and who are busiest when the reporting requirements are
2 highest, the system dispatchers and the line crews whose main task is to
3 respond to trouble calls and restore service.

4 **Q: What plans do CL&P and UI have to improve the quality of the data**
5 **collected on outages?**

6 A: CL&P states that it "works continually to improve the quality of the data it
7 collects on outages." CL&P's plans for future improvements include training
8 of system dispatchers and integration of its supporting information systems
9 and database, which should reduce the reliance on manual input by system
10 dispatchers and reduce data inconsistencies. (OCC-CL&P-26)

11 UI, on the other hand, believes that there is no reason to improve its
12 outage reporting system:

13 ...UI believes that the quality and quantity of the reliability data it
14 collects is second to none in the electric utility industry. (OCC-UI-17)

15 and:

16 Based on discussions with many other utilities, UI believes that the
17 accuracy of reliability data it collects is excellent. (OCC-UI-18)

18 UI's unrealistic faith in its outage data collection system is contradicted
19 by its own internal report, Storm Floyd Critique Notes (Attachment to OCC-
20 UI-4-2). These notes indicate significant data problems during the storm
21 center operation, including:

- 22 • Failure to show accurate customer counts by distribution device on the
23 utility's GIS system (#3 and #4);
- 24 • Mistakes in eliciting information from customer calls (#17);
- 25 • Delay in entering trouble reports in the computer system (#18); and
- 26 • Problems in coordinating computer system operations with storm center
27 operations (#22)

1 It appears from the experience of UI's own employees that its data-collection
2 system needs improvement.

3 **IV. Distributed Utility Planning**

4 **Q: Does either Company design its DSM programs to target specific areas**
5 **in need of T&D upgrades or improved reliability?**

6 A: No.

7 **Q: Why does CL&P reject targeted DSM?**

8 A: CL&P acknowledges that targeted DSM may be useful, but claims that its
9 past efforts have been largely unsuccessful. According to its response to
10 OCC-CL&P-24, the DSM savings were not sufficient to defer or avoid T&D
11 expenditures, and could not be large enough unless the utility provided
12 excessive customer incentives or made participation mandatory.

13 CL&P did not provide any detail on its past efforts. Therefore, it is not
14 possible for me to evaluate its claims at the present time. The agenda for
15 further proceedings or roundtable discussions should include an in-depth
16 review of CL&P's experience in this area to determine how targeted DSM
17 can be made more effective through improved selection of T&D projects,
18 proper identification of the target area, and enhanced marketing and customer
19 incentives.

20 **Q: What reasons does UI give for rejecting targeted DSM?**

21 A: Similar to CL&P, UI contends that the savings will be too small and
22 uncertain to affect specific T&D plans. But unlike CL&P, UI indicates a
23 complete unwillingness to design DSM to target specific areas. In addition,
24 UI indicates a preference for last minute planning, upgrading equipment only

1 when it becomes unreliable, rather than planning based on load growth
2 projections. As UI states in its response to IR OCC-UI-14:

3 ...The use of consistent customer incentives across UI's service area
4 minimizes the complexity of program design and customer
5 communications.

6
7 UI makes decisions about the scope and timing of T&D additions based
8 on reliability concerns alone. UI would not make such decisions based
9 on the relatively small and somewhat uncertain local impact of targeted
10 conservation or load management.

11 **Q: Does this complete your supplemental testimony?**

12 A: Yes.

13

14